

Invitation for International Tender

BIMAN BANGLADESH AIRLINES LIMITED

| | | | |
|---------------------------------|---|---|--------------------|
| 01. | Invitation for | Selection of Agency for Repair/ Overhaul of GTCP331-500 APU | |
| 02. | Invitation Ref No. | 30.34.2600.37.28. 002.18.104 | |
| KEY INFORMATION | | | |
| 03. | Procurement Method | Open Tender Method | |
| FUNDING INFORMATION | | | |
| 04. | Budget and Source of funds | Biman own fund | |
| PARTICULAR INFORMATION | | | |
| 05. | Tender Package Name | Selection of Agency for Repair/ Overhaul of GTCP331-500 Auxiliary Power Unit | |
| Date | | | |
| 06. | Tender Publication Date | 17 May, 2018 | |
| | | Date | Time |
| 07. | Tender Closing Date & Time | 20 June, 2018 | 14:00 Hrs LT (BST) |
| | | 20 June, 2018 | 14:30 Hrs LT (BST) |
| 08. | Tender Opening Date & Time | Note: If any unavoidable circumstances arise at the date of closing/ opening of the tender, the next working day will be scheduled for receiving/opening the tender. | |
| 09. | Name & Address of the office | Biman Engineering Hangar, Hazrat Shahjalal Int'l Airport, Dhaka | |
| 10. | Tender Schedule will be available at Free of charge at the locations: | a) Downloading from Biman website http://www.biman-airlines.com/corporate/tender | |
| 11. | Receiving Tender Document | a) Office of the Director Engineering & Material Management, Biman Hangar Complex, Hazrat Shahjalal Int'l Airport, Dhaka-1229, Bangladesh or b) Tender offer may be dropped in the Tender Box that will be placed only on the closing date at reception of Bangladesh Airlines Training Center (BATC), Hazrat Shahjalal Int'l Airport, Dhaka. c) Offer/proposal may also be sent by email to the address: gtcp331tender@bdbiman.com | |
| 12. | Opening Tender Document | a. Conference Room, 2 nd Floor, Bangladesh Airlines Training Center (BATC), Hazrat Shahjalal Int'l Airport, Dhaka-1229, | |
| 13. | Place/ Date/ Time of Pre-Tender Meeting (Optional) | No pre-tender meeting will be held | |
| 14. | Eligibility of Tenderer | The Tenderer must be a holder of Certificate of Approval issued by FAA and/or EASA with local regulatory Authority and capable of in-house repair and overhauling of GTCP331-500 APU. The tenderer must agree to comply with any directive(s)/instruction(s) issued by the Civil Aviation Authority of Bangladesh (CAAB). | |
| 15. | Brief Description of works | Repair/ Overhaul of GTCP331-500 APU (fitted to B777 Aircraft) | |
| PROCURING ENTITY DETAILS | | | |
| 16. | Name of Official Inviting Tender | Kh. Sazzadur Rahim Group Captain (Retd) | |
| 17. | Designation of Official Inviting Tender | Director Engineering & Material Management | |
| 18. | Address of official Inviting Tender | Biman Engineering Hangar, Hazrat Shahjalal Int'l Airport, Dhaka, BD | |
| 19. | Contact details of official inviting Tender | Tel. 880-2-8901313 Fax. 880-2-8901639 E-mail : debiman@bdbiman.com | |
| 20. | Biman Bangladesh Airlines reserves the right to accept or reject any or all tenders | | |

Visit website: www.biman-airlines.com

Director Engineering & Material Management.